

ON FIRE
CATCH ON
EDGES MAKES
GAPS.

KILN BACK


KILN BACK

NEET BIZMORE GAP AT

EDGES PUT IN.

GLASS WOOD + REMOVE
SO GAP.

111 + C103 BLUE
TOP BIZ.




ALL GLASS
500x80
EDED FIRST
RIGHT CUT
DOWN + HIGHER
MAX 105

STAIN.
(ABOVE DICRO REVERSE
SO SAME DIRECTION)
ALL STAIN
UP.

DICRO
DOWN
EXPT ABOVE
DICRO
STAIN DOWN

BELONG DICRO
JUST BIT OF
C103 BLUE

ON 1 LAYER OF 75



HT AZ 82
ASSEMBLY ERROR. - UNDER DICRO LOTS STAIN SHOULD BE LIGHT RIB
THEN HEAVY STAIN UNDER THAT TO BRING OUT DICRO

1037 98^a 52 RD $\frac{1}{2}$ IN TO ~~OUT~~ IN KB 3/8/05 75+SPEC III W278 YES
 TD $\frac{1}{2}$ OUT BD OUT W278 + C103

807 700 TR 34m MOVING DOWNSCAFFOLD
 932 715 MOVING DOWN BUT A Z HINKOW EDGES.


12-53 775 BACK NOT TO BAD FOR GAPS BUT
 783 FRONT FEW GAPS 5-10...
 (HOLD) STARTING TO FUZE - PREP BUBBLES

DISH WASH WAS USED
 75 SPECTRUM PICO
 + 1 LAYER
 EXZADURASE PICO
 EXZADURASE
 ONLY SCIENT
 REACHY - GAP UPPER CAST
 BEND DOWN

W274
 W265
 W263
 PTC
 3141

208 783 LOST LOTS MORE SMALL GAPS OPENING UP FRONT RIGHT
 313 804 MORE GAPS MOSTLY ON FRONT RIGHT BODY FUZING

422 827 GAPS NOT
 EVEN MORE GAPS AS SCUMP DOWN. BUT DICO LOOKS OK



659 880 OK START TO POOL BUBBLES FORMING. ABOUT ON 20 SOAF 1000^o
 758 1000 MOST BUBBS RISE. NOT POOLED ALLWAY. 30m TUGO + NOT FLAT

831 1000 BUBBS RISING POOLED TO LEFT BUT ~~NOT~~ LEVEL BUT NOT FLAT
 900 1000 MOST BUBBS AT SURFACE - NICE CURVE
 945 1000 OK POOLED

11-00 598 AND CLIMBING / 11-03 61500.

1106 AM 504 / 11.10 PM 387 SP 367 / 284 1021 10.21 PM 284 ALL OFF NOT OPENED
 518
 146 NOT OPENED
 1451 HA / 307 104 307 1040 LOOKS GOOD AND OK COLOURS 4.600
 618 R. 11.10 25 350 350 x 500 500

ON FINISH SOME DEVIT WITH IN A GLASS
FEW PATCHES BAD. STENTS UP IN SOME
LIGHT + BACE LACER 75 SOME DEVIT AT INTERFACE

SO SHOULD BE GRIND OFF SCUM FROM OLD GLASS
POSS DUE TO SURFACE SCUM FROM OLD GLASS
+ GAPS PRIOR TO FUSE

NETT CLEAN
1ST DW EXTRA SOAP
2ND NORMAL DOTH
WAT TEMP.
OR USE BRICK CLEANER ON
GLASS FIRST

BRICK CLEANER
WIPED ON GLASS
ON SPRAYED
IN
WASH MARKS IN CONTAINER

NEED TO BE
LEFT FOR + DOUBLE
ON HITTER.
+ BLACK UNDER DIRM WITH
BUT STOP DIRM SO JUST BRICK
SOME +
MUCH LIGHTER
RIBB.

ON FIN
DIPLO
DOWN.
STAIN BELOW
BLACKS OUT
DIPLO ON 75

W 278 RESULT WORKED V. WELL

NEED:

NO OR LITTLE STAIN/ON DICRO
DICRO.

ON 75 DICRO STOP 10-7~ 1502 GOOD

DICRO
GREEN/BLUE

75 + DICRO
STAIN NO PINO
STAIN/DICRO LAYER
BLACK BOTH
SIDE

BUBBLES
THROUGHOUT
SUE PIT
TO BAD
ON TO BIT
IN BEHIND
AREAS

BLACK LAYER
NEED TO BE
RIGHT

BACK

FRONT

BACK

FRONT

SOLD AT
BUSINESS DESIGN
CENTRE ESCORTION 510
I AM 06
SOLD ON BIG
ONE BEFORE

W T AFTER
MIL EDGES CAPED
OFF 44 LB.

95 BACK
87 FRONT